

# Instruction for hydraulic filter

BM-795120

ANV152


EN



Original design



Replacement design



Fit the new hydraulic filter part no. BM-795120 in the following order:

**NOTE:**

The spacer sleeve is positioned on top.

The filter is positioned under the spacer sleeve.

Recommended change interval: 500 hours

2021-11-08



**Olsson Parts**

Olssons i Ellös AB • Tel. +46 304-751010  
Slätthultsvägen 12 • S-474 31 Ellös  
www.olssonparts.com • order@olssonparts.com